



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
August 5, 2009

Reviewed: RK

| | |
|--|---------------------------------------|
| Mine Name: Nielson Sandstone | Permit Number: M/023/0012 |
| Operator Name: Ash Grove Cement Company | Inspection Date: July 14, 2009 |
| Inspector(s): Wayne Western | Time: 3:00 pm to 3:20 pm |
| Other Participants: none | Mine Status: ACT |

| Elements of Inspection | Evaluated | Comment | Enforcement |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages / Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

This was a routine inspection.

Bond Amount:

\$1,332,126.00 escalated until November 7, 2009.

Permit Fees:

Paid for 2009

Inspection Summary:

The site is an active operation. The site was stable, no problems with slope stability were found.

Conclusions and Recommendations:

The Division should continue to monitor the site. In November 2009, the Division should escalate the bond.

Inspection Date: July 14, 2009

Page 2 of 3

M/023/0012

Directions to Site:

Turn west approximately ½ mile north of mile maker 14.

Inspector's Signature

Wayne Newton 08/10/2009

WHW::pb

cc: Bruce Newell

Jerry_Mansfield@BLM.gov

O:\M023-Juab\M0230012-NielsonSSQuarry\Inspections\Insp_08052009.doc



Equipment on site

